

1 Q. **Tab 14; Volume II: Diesel Genset Replacements Port Hope Simpson and**
2 **Charlottetown, Labrador**

3 Hydro states that diesel engines are normally refurbished every 20,000 hours of
4 operations. Please confirm that only one overhaul has been completed on Unit
5 2073, which is listed as having 51,399 hours in Table 1, and provide an explanation
6 for the unit not being refurbished within Hydro's maintenance practices.

7

8

9 A. Upon further investigation, Unit 2073 has been overhauled twice since being
10 installed in 2005. The first overhaul was performed in 2009 with 22,019 hours on
11 the unit. The second overhaul was completed in 2014 with 40,443 hours on the
12 unit. The next overhaul is anticipated to be required in 2018. Hydro apologizes for
13 the error.