

1 Q. **Reference: Failure Investigation Report – L3501/2 Pole Assembly Turnbuckle Failure – Failure**
2 **Event February 2021 in Labrador (2021 Turnbuckle Failure Report).**

3 Assume the January and February, 2021 Labrador outage events had occurred with the LIL in full
4 rated bipole operation, with the Holyrood Generating Plant removed from service and no new
5 generation added, how would the supply of power to customers on the Island Interconnected
6 system been impacted by the 2021 outage events in Labrador?

7

8

9 A. Please refer to Newfoundland and Labrador Hydro's response to NP-NLH-063.