

1 Q. Please confirm that while there have been cracks found in the refurbished welds, no ruptures
2 have occurred in Penstock 1 since September 2019.

3

4

5 A. It is confirmed. No ruptures have occurred in Penstock 1 since September 2019.