1	Q.	Reference: Project 1 Rewind Stator (2025–2026) – Hinds Lake, Attachment 2, page 15 of 16.
2		Qualitrol's Partial Discharge Test Report recommended retesting the unit in 6 months. Did
3		Hydro retest the unit as recommended? If yes, what were the results? If no, why not?
4		
5		
6	A.	No. Due to limited resource availability, Newfoundland and Labrador Hydro ("Hydro") has not
7		completed a retest of this unit to date. Hydro intends to retest the unit and review the data with
8		the support of a consultant in September 2024. The results of the unit retest are intended to
9		better inform the discussion with Qualitrol and will not affect Hydro's recommendation to
10		proceed with the replacement of the stator winding.