

Q. **Reference: Program 1: Wood Pole Line Management (2027), Appendix A, Plan for Wood Poles Greater than 55 years old**

Further to Table 1 on page A-2, provide a second table for each transmission line identifying the number of poles to be replaced by year.

A. Please refer to Table 1 for the requested information. The number of poles to be replaced is subject to change based on how survivor curves may change over the next 20 to 30 years.

Table 1: Estimated Number of Poles to be Replaced per Transmission Line¹

Line	Year	Estimated Number of Poles Replaced
TL203	2027	72
	2037	82
	2047	167
TL201	2034	117
	2044	103
	2054	193
TL218	2027	4
	2037	46
	2047	41
TL212	2028	100
	2038	68
	2048	55
	2058	112
TL223	2031	49
	2041	35
	2051	263
TL222	2035	78
	2045	92
	2055	656
TL224	2027	2
	2037	134
	2047	83
	2057	585

¹ The number of poles associated with TL203 and TL220 in Table 1 on page A-2 of Appendix A, Plan for Wood Poles Greater than 55 years old, was reported in error. The revised pole count is reflected in the table.

Line	Year	Estimated Number of Poles Replaced
TL210	2034	217
	2044	124
	2054	215
TL220	2027	109
	2032	22
	2042	29
	2052	69
TL215	2031	94
	2041	75
	2051	175
TL245	2035	34
	2045	29
	2055	207
TL225	2029	5
	2039	4
	2049	5
	2059	34
TL221	2034	64
	2044	59
	2054	451
TL226	2033	102
	2043	80
	2053	686
TL227	2029	3
	2039	164
	2049	90
	2059	643