1	Q.	RE: p. B-26 Upgrade – TL 227 – (69 kV Berry Hill – Daniel's Harbour)			
2		(\$496	,000)		
3					
4		18.1	Response to Information Request PUB 28.3, 2001 Capital Budget,		
5			indicated that to September 30, 2000 there had been no momentary		
6			and no sustained outages during 2000 on TL227. How many outages		
7			occurred between September 30 and December 31, 2000? Can all of		
8			these be directly attributed to damage due to salt contamination?		
9					
10		18.2	When the 2001 Capital Budget was presented to the Board, it was		
11			indicated that there were no future commitments with regard to this		
12			line. When was it determined that a total of 25 km. of line required		
13			upgrading? By whom was the determination made? What was the		
14			rationale for this additional upgrade? If a written report was produced,		
15			provide a copy.		
16					
17		18.3	What are the plans of the company with regard to the remaining 60		
18			km. of line?		
19					
20	A.	18.1	There were no outages on TL 227 from September 30 to December		
21			31, 2000.		
22					
23		18.2	It was determined in January 2001 that a total of 25 km of line		
24			required upgrading. The determination was made by Operations		
25			personnel in consultation with Engineering. The rationale for this		
26			additional upgrade is based on the findings of a more detailed		
27			investigation of TL 227 which was carried out in preparation of an		

PL	JB-18.0 Revised
2001 General F	Rate Application

<u>-</u>		2001 General Rate Application
_		Page 2 of 2
1		assessment report entitled "Northern Peninsula Upgrading
2		Recommendations - January 2001". A copy of this report is attached.
3		
4	18.3	Currently, Hydro has no plans regarding the remaining 60 km of line.