1	Q.	RE: p	p. B-28 Replacement of Insulators - TL229 (69 kV Wiltondale -		
2		Glenburnie) (145,000)			
3					
4		20.1	What is the total purchase price of the 1050 insulate	ors being	
5			replaced? What is the labour cost? What other co	sts are involved?	
6					
7		20.2	How many outages occurred on this line in 1998? in	n 1999? in 2000?	
8			How many of these can be attributed to failure of in	sulators? How	
9			many can be attributed to other causes?		
10					
11					
12	A.	20.1	The budget proposed for replacement of insulators	on TL 229 actually	
13			covers 150 units. The figure of 1050 units quoted i	n Hydro's 2002	
14			Capital Budget submission in incorrect. Specific co	sts budgeted for	
15			purchasing and installing the replacement insulator	s are as follows:	
16					
17			Material Supply	\$35,000	
18			Labour	20,000	
19			Engineering	20,000	
20			Project Management/Environment	30,000	
21			Inspection & Commissioning	10,000	
22			Corporate O/H, IDC, Esc., Contingency	<u>30,000</u>	
23			Total	\$145,000	
24					
25		20.2	There were no sustained outages on TL 226 in 199	8, 1999 and 2000.	