

1 Q. RE: p. B-29 Replacement of Insulators – TL 211 (230 kV Massey Drive –
2 Bottom Brook)

3

4 21.1 What is the total purchase price of the 6700 insulators being
5 replaced? What is the labour cost? What other costs are involved?

6

7 A. 21.1 Specific costs budgeted for purchasing and installing the replacement
8 insulators are as follows:

9

10	Material Supply	\$220,000
11	Labour	130,000
12	Engineering	32,000
13	Project Management/Environment	62,000
14	Inspection & Commissioning	12,000
15	Corporate O/H, IDC, Esc., Contingency	<u>113,700</u>
16	Total	\$569,700