

1 Q. RE: p. B-30 Replacement of Insulators – TL 228 (230 kV Buchans – Massey
2 Drive) (\$450,000)

3

4 22.1 What is the total purchase price of the 3700 insulators being
5 replaced? What is the labour cost? What other costs are involved?

6

7 A. 22.1 Specific costs budgeted for purchasing and installing the replacement
8 insulators are as follows:

9

10	Material Supply	\$160,000
11	Labour	120,000
12	Engineering	30,000
13	Project Management/Environment	46,000
14	Inspection & Commissioning	8,000
15	Corporate O/H, IDC, Esc., Contingency	<u>86,100</u>
16	Total	\$450,100