

1 Q. RE: p. B-40 Replace Conductor/Poles - Burgeo (\$300,000)

2

3 29.1 Provide the SAIFI and SAIDI figures for the Burgeo area for 1999,  
4 2000, and to June 30, 2001.07.12. (*sic*)

5

6

7 A. 29.1 The SAIFI and SAIDI figures for the Burgeo area are as follows:

8

<b>Index</b>	<b>1999</b>	<b>2000</b>	<b>YTD (2001/06/30)</b>
SAIFI <sup>(1)</sup>	0.48	3.24	5.70
SAIDI <sup>(2)</sup>	0.30	14.04	1.51

9

10 (1) SAIFI – Total Customer-Interruptions  
11 Total Customers Served

12

13 (2) SAIDI - Total Customer-Hours of Interruptions  
14 Total Customers Served