

1 Q. **Re: p. B-38** Have there been any incidents associated with the failure of  
2 station post insulators since regular inspections were instituted?

3

4

5 A. There have been no failures of insulators on the disconnects since regular  
6 inspections were started. Any insulators that are found to be faulty are  
7 replaced, immediately. However, inspections of the insulators do not  
8 preclude the fact that the safety hazard still exists. Installing the motor  
9 operators will eliminate the risks associated with manual switching.