1	In reference to Schedule "B", page 53 of 82 – Trunk Feeders / Water Street / St. John's:	
2		, L
3	Q.	Please provide a rating as to the deterioration of the oil-filled switches and the
4		platform mounted transformers. Please provide any pre-project repairs undertaken
5		in this area in the last five years.
6		
7	A.	Newfoundland Power does not rate the switches and transformers as to the level of
8		deterioration.
9		
10		Following is a list of known pre-project repairs within the last five years for the
11		Buchanan Street and Waldegrave Street switches budgeted to be removed in 2003.
12		
13		1. Buchanan Street - Removed and reconditioned in 1998.
14		
15		2. Waldegrave Street - One new cable-head installed in 2001.
16		
17		There were no pre-project repairs within the last five years for the St. John's Lane switch
18		which is also budgeted to be removed in 2003.
19		
20		