

In reference to the projects listed in Schedule “B”, page 43 of 66, of that same budget:

**Q. Please provide the reasons for the interruptions in Trepassey for the SAIFI and SAIDI figures stated.**

A. Table 1 below provides a summary of the reasons for unscheduled distribution outages on distribution feeder Trepassey-01 for the period July 1996 to June 2001.

<b>Table 1 Trepassey-01: Reasons for Unscheduled Distribution Outages July 1996 to June 2001</b>	
<b>Reason for Outage</b>	<b>No. of Interruptions</b>
Broken or Defective Equipment	172
Salt Spray	26
Wind	13
Lightning	17
Unexplained	10
Miscellaneous	9
Sleet	8
Preventive Maintenance	4
Overloaded Equipment	2
Animals	2
Snow	2
<b>TOTAL</b>	<b>265</b>