

Re Volume III, Distribution Lightning Arrestors, Appendix 2, Attachment B

Q. Have there been any failures due to lightning strikes on transformers equipped with lightning arrestors. Please give details.

A. Newfoundland Power is aware of only two transformers with lightning arresters that have experienced failures. These failures were attributed to direct lightning strikes and the lightning arrestor does not offer protection against this situation.