1	Q.	<u>GENERATION - HYDRO</u>
2		
3		Rattling Brook Hydro Plant Refurbishment (Clustered) - \$18,242,000
4		
5		PUB 1.0 NP
6		
7		In other projects where woodstave penstocks have been replaced, either within
8		Newfoundland Power Inc. service territory or in other jurisdictions, have there been
9		follow-up reports that provide an evaluation of the actual state of the penstock that
10		has been replaced? If so, please provide these reports.
11		
12	A.	There have not been any follow-up reports that provide an evaluation of the actual state
13		of the penstocks that have been replaced within Newfoundland Power's service territory.
14		
15		The Company is not aware of reports from other jurisdictions comparing the actual
16		condition of demolished penstocks with the condition indicated by engineering
17		inspections and assessments.