

NEWFOUNDLAND AND LABRADOR

BOARD OF COMMISSIONERS OF PUBLIC UTILITIES

120 Torbay Road, P.O. Box 21040, St. John's, Newfoundland and Labrador, Canada, A1A 5B2

E-mail: traceypennell@nlh.nl.ca

2016-09-08

Ms. Tracey Pennell Senior Counsel Newfoundland and Labrador Hydro P.O. Box 12400 Hydro Place, Columbus Drive St. John's, NL A1B 4K7

Dear Ms. Pennell:

Re: Newfoundland and Labrador Hydro – 2017 Capital Budget Application Requests for Information

Enclosed are Information Requests PUB-NLH-001 to PUB-NLH-020 regarding the above-noted application.

If you have any questions, please do not hesitate to contact the Board's Legal Counsel, Ms. Jacqui Glynn, by email, jglynn@pub.nl.ca or telephone (709) 726-6781.

Yours truly,

Cheryl Blundon Board Secretary

TT

Enclosure

ecc Newfoundland & Labrador Hydro

Mr. Geoff Young, E-mail: gyoung@nlh.nl.ca

NLH Regulatory, E-mail: NLHRegulatory@nlh.nl.ca

Newfoundland Power Inc.

Mr. Gerard Hayes, E-mail: ghayes@newfoundlandpower.com

Mr. Liam O'Brien, E-mail; lobrien@curtisdawe.com

Consumer Advocate

Mr. Thomas Johnson, Q.C., E-mail: tjohnson@odeaearle.ca

Ms. Colleen Lacey, E-mail: clacey@odeaearle.ca

Industrial Customer Group

Mr. Paul Coxworthy, E-mail: pcoxworthy@stewartmckelvey.com

Mr. Dean Porter, E-mail: dporter@poolealthouse.ca

Vale Newfoundland and Labrador Limited

Mr. Thomas O'Reilly, Q.C., E-mail: toreilly@coxandpalmer.com

Mr. Denis Fleming, E-mail: dfleming@coxandpalmer.com

Mr. Jason Callan, E-mail: jason.callan@vale.com

Praxair Canada Inc.

Ms. Sheryl Nisenbaum, E-mail: sheryl_nisenbaum@praxair.com

Mr. David Meade, E-mail; dave_meade@praxair.com

Teck Resources Limited

Mr. Larry Bartlett, E-mail: larry.bartlett@teck.com

Ţ	IN THE MATTER OF			
2	the Electrical Power Control Act, 1994,			
3	SNL 1994, Chapter E-5.1 (the " <i>EPCA</i> ")			
4	and the Public Utilities Act, RSNL 1990,			
5	Chapter P-47 (the "Act"), as amended, and			
6	regulations thereunder; and			
7				
8	IN THE MATTER OF			
9	an Application by Newfoundland and Labrador Hydro			
10	for an Order approving:			
11				
12	1) its 2017 capital budget pursuant to s.41(1) of the Act			
13	2) its 2017 capital purchases and construction projects i			
14	excess of \$50,000 pursuant to s.41(3)(a) of the Act;			
15	3) its leases in excess of \$5,000 pursuant to s.41(3)(b)			
16	of the Act;			
17	4) its estimated contributions in aid of construction for			
18	2017 nursuant to s 41(5) of the 4ct			

PUBLIC UTILITIES BOARD REQUESTS FOR INFORMATION

PUB-NLH-001 to PUB-NLH-020

Issued: September 8, 2016

Tab B; Volume l	l: Capital Budget Summary With Multi Year Projects Separated
PUB-NLH-001	Page B-5 Multi-year Projects Commencing in 2017 shows the project "Replace Exciter Controls Units 1 to 6 – Bay d'Espoir" with expenditures only in 2017 and 2018 whereas the project report located at Tab 2 budgets expenditures yearly until 2020. Please update the table on page B-5 to reflect the multi-year expenditures for this project.
PUB-NLH-002	Page B-6 Multi-year Projects Commencing in 2016 states the project "Upgrade Circuit Breakers – Various Sites (2016-2020)" has expenditures concluding in 2018. In Hydro's 2016 Capital Budget Application this project had budgeted expenditures yearly until 2020. Please update the table on page B-6 to reflect yearly expenditures for this previously approved project.
C-80, Volume I:	Replace Power Transformers
PUB-NLH-003	When in 2014 did the Oxen Pond grounding transformer fail?
PUB-NLH-004	Please confirm that the justification for the replacement of the Oxen Pond transformer is failure of the transformer, not a Degree of Polymerization of cellulose insulation paper less than 400 or a poor dissolved gas analysis.
PUB-NLH-005	In its 2015 Capital Budget, Hydro provided a list of planned work for transformers in 2017, 2018 and 2019. Please provide an update on the work initially planned for 2017, 2018 and 2019.
C-89; Volume I:	Replace Vehicles and Aerial Devices
	s that meet the criteria are being replaced. In addition, one light duty vehicle the list because it met the replacement criteria."
PUB-NLH-006	Please explain the statement "In addition, one light duty vehicle was added to the list because it met the replacement criteria."
D-46; Volume I:	Refurbish Sump Level System for Powerhouse 2
PUB-NLH-007	Please provide the source containing the different technologies for the measurement of water levels in sump pits referenced as "Error! Reference source not found." on page D-53.

Tab	3; Volume I	II: Water System Replacements - Bay d'Espoir and Cat Arm			
B Hydr H " S w	Hydro states at page 16: "A cooling water study completed in 2002 concluded that the most effective solution was to replace the existing fouled piping with corrosion and foul resistant stainless steepipe."				
3 The	2002 study ugh 6.	referenced was in relation to the Bay d'Espoir water systems for Units 1			
	-NLH-008	Please confirm if Hydro has conducted any follow up studies for the water systems proposed to be replaced in the current application. If yes, please provide a copy.			
5 Tab	12; Volume	II: Install Asset Health Monitoring System			
)	-NLH-009	Is Hydro aware of any other utilities or jurisdictions that have installed Asset Health Monitoring Systems?			
<u>2</u> 3	-NLH-010	Please explain how Hydro will evaluate the benefits it expects to achieve through the use of automated asset health monitoring systems.			
	14; Volume rador	e II: Diesel Genset Replacements Port Hope Simpson and Charlottetown,			
	-NLH-011	Hydro states that diesel engines are normally refurbished every 20,000 hours of operations. Please confirm that only one overhaul has been completed on Unit 2073, which is listed as having 51,399 hours in Table 1, and provide an explanation for the unit not being refurbished within Hydro's maintenance practices.			
PUB	-NLH-012	Please provide a definition for refurbishment, rebuild and overhaul as related to gensets.			
5 7 PUB 3))	-NLH-013	Hydro notes the total capacity of Charlottetown is 3,205 kW yet Hydro states the firm capacity, as defined in Section 3.1.1, is 845 kW. Please explain why the 910 kW and the 725 kW mobile gensets are not considered when determining firm capacity.			
	-NLH-014	Please update the Single Line Diagrams in Appendix A and Appendix C to reflect the existing genset ratings provided on page 8.			

1 2	Tab 16; Volume	II: Transmission Line Upgrades				
3 4 5	PUB-NLH-015	Please explain how Hydro ranks and selects which transmission lines to upgrade in a given year.				
6						
7 8	Tab 28; Volume	III: Replace Automation Equipment - Mary's Harbour				
9	Hydro states:					
10	3.2.5 Historical Information					
11		ted a program in 2015 to replace 25 PLCs at 4 diesel plants due to				
12	obsolescence.	The first PLC replacements were completed at L'anse au Loup in 2015. Port				
13	Hope Simpso	on will be completed in September 2016 and Hawke's Bay and Ramea will be				
14	completed in	2017."				
15	•					
16	PUB-NLH-016	Is the proposed equipment replacement solely for automation purposes or does				
17		it serve other requirements similar to those that would have justified the				
18		projects noted in the Historical Information section of this proposal?				
19						
20	PUB-NLH-017	Has Hydro performed a cost benefit analysis regarding the replacement of the				
21		automation equipment?				
22	DIID 311 II 040	T T T T T T T T T T T T T T T T T T T				
23	PUB-NLH-018	Is Hydro proposing to continue the automation of other diesel plants?				
24 25						
25	T-1-04-X/-1	TITLE D. A.C. THE A.				
26 27	1 ab 21; volume	III: Line Depot Condition Assessment and Refurbishment Strategy				
27 28	PUB-NLH-019	Page 0.10; Plages explain why "downstition and account of the satisfaction				
29	I OID-IVLIATE-ULD	Page 9-10: Please explain why "demolition and removal costs of the existing building" is listed as an additional cost item to refurbish the building but is				
30		excluded as an additional cost item to replace the building.				
31		exercised as an additional cost tem to replace the bunding.				
32	PUB-NLH-020	Page 9: Please provide details of operating and maintenance (life cycle) costs				
33	Z OD TIME VMU	to refurbish the building which are over and above what would be expected to				
34		maintain a new building.				

DATED at St. John's, Newfoundland this 8th day of September, 2016.

BOARD OF COMMISSIONERS OF PUBLIC UTILITIES

Per Cheryl Blundon
Board Secretary