Page 1 of 1

| 1 | Q. | Volume 1 (1 st Revision), Chapter 3: Operations | | | | | | |
|----|----|--|--|--|--|--|--|--|
| 2 | | Please provide a revised table for Table 3-7 Gas Turbine Performance to UFOP for | | | | | | |
| 3 | | the years 2007-2016 for each of (i) the Hardwoods gas turbine, (ii) the Stephenville | | | | | | |
| 4 | | gas turbine, (iii) the Holyrood CT, and (iv) the Happy Valley gas turbine that includes | | | | | | |
| 5 | | a comparison to the national CEA average. (Volume I (1st Revision), Chapter 3: | | | | | | |
| 6 | | Operations, Page 3.12, Table 3-7) | | | | | | |
| 7 | | | | | | | | |
| 8 | | | | | | | | |
| 9 | A. | Please refer to Table 3-7 for the Gas Turbine Performance for the years 2007 to | | | | | | |
| 10 | | 2016 for each of (i) the Hardwoods gas turbine, (ii) the Stephenville gas turbine, (iii) | | | | | | |
| 11 | | the Holyrood Gas Turbine, and (iv) the Happy Valley gas turbine. | | | | | | |

Table 3-7 Gas Turbine Performance to UFOP

| | 2007 | 2008 | 2009 | 2010 | 2011 | 2012 | 2013 | 2014 | 2015 | 2016 |
|--------------------------|-------|-------|-------|-------|-------|---------------------|-------|-------|-------|-------|
| Hardwoods | 11.56 | 8.85 | 11.09 | 8.01 | 6.30 | 16.65 | 14.42 | 19.42 | 5.53 | 7.83 |
| Stephenville | 4.72 | 8.87 | 11.18 | 5.36 | 15.2 | 100.00 ¹ | 50.00 | 13.73 | 15.71 | 15.40 |
| Holyrood GT | - | - | - | - | - | - | - | - | 3.06 | 1.65 |
| Happy Valley | 12.41 | 31.20 | 9.46 | 14.55 | 6.01 | 20.56 | 2.56 | 0.01 | 14.56 | 5.03 |
| CEA Average ² | 4.95 | 13.97 | 16.95 | 9.11 | 18.01 | 14.79 | 13.22 | 11.07 | 23.08 | 11.83 |

¹ Stephenville Gas Turbine was on a forced outage from Dec 2011 to July 2013. ² 0-10% operating factor classification.