1	Q.	Reference: Supply Cost Deferrals 2015, 2016 and 2017 Application Evidence,
2		Appendix B, Specific Examples of the Requirement for Standby Generation, page
3		3, lines 18-21.
4		
5		"During this week, standby generation was required to support both load and Island
6		spinning reserves on November 3, 2015 and November 4, 2015. Island spinning
7		reserve would have been below the level required to sustain the loss of the largest
8		online unit for both the morning and evening peak on both days."
9		
10		At page 2 of 31 of Appendix L (Revision 2), the reason stated for operation of the
11		Holyrood GT on both November 3 <sup>rd</sup> and 4 <sup>th</sup> was "Planned Avalon Peninsula
12		transmission outages." Please confirm why the Holyrood GT was operated on those
13		days.
14		
15		
16	A.	Hydro confirms that the Holyrood GT was operated for planned Avalon Peninsula
17		transmission outages on November 3 and November 4, 2015.