

1 **Re: General**

2 Q. Please provide a list of all capital projects (including project identifier, where
 3 applicable) to which senior management (non-executive) time was charged
 4 between 2004 and 2008, including the number of hours charged to each.

5
 6

7 A. Senior management did not charge any time to regulated capital projects in
 8 2004 and 2005. The projects for 2006, 2007 and 2008 to date are listed in
 9 the following table.

Capital Projects to which Senior Management Charged Time			
Year	Project Number	Project Name	Hours
2006	12540301	Replace Energy Management System	408.5
	12840501	Replace Underground Fuel Tanks - Cat Arm	12.5
	12870501	Replace Penstock - Snook's Arm	62.5
	13250510	Purchase Mobile Oil Reclamation Unit	1.0
	13460605	Installation of Fall Arrest Equipment - Hydro facilities	16.0
	13490506	Transmission Interconnection - Duck Pond Mine Site	15.0
	13490605	Replace Insulators TL231 - (230kV Bay d'Espoir - Stoney Brook)	108.5
	13490608	Wood Pole Line Management Program	17.0
	13500503	Rencontre East Interconnection	70.0
	13500607	Insulator Replacement - Bottom Waters (Lines 7,8)	25.0
	13500608	Insulator Replacement - Farewell Head (Lines 4,6)	22.0
	13500609	Insulator Replacement - South Brook TL246 (Lines 5,7)	53.0
	13500610	Insulator Replacement - Bottom Waters (Lines 4,6)	57.5
	13500611	Replace Poles - Bottom Waters Line 1	8.0
	13500612	Install Poles - Rocky Ridge	85.5
	13960506	Dome Mountain Service -Coast Guard	56.5
	13970606	Upgrade Distribution - Black Tickle	49.5
	13970607	Replace Poles - Nain	6.0
	14110606	Construct New Diesel Plant - St. Lewis	16.5
	20840602	Island Pond Development - Feasibility Update	101.0
20840603	Portland Creek Development -Feasibility Study	11.0	
20890601	West Coast Communications Study	69.0	
Total 2006			1,271.5

Capital Projects to which Senior Management Charged Time			
Year	Project Number	Project Name	Hours
2007	12420702	Replace Battery Banks 48VDC	3.0
	12420710	Microwave Site Refurbishing	2.0
	12840701	Access Road Improvements - Upper Salmon	12.0
	12930701	Access Road Improvements - Burnt Dam	15.0
	12960601	Replace Superheater Unit 2 - Holyrood	41.5
	12960701	Replace Unit 2 Main Steam Stop Valve - Holyrood	131.0
	13320702	Replace Main Fuel Line - Hardwoods Gas Turbine	64.0
	13320703	Replace Fuel Piping - Stephenville Gas Turbine	78.5
	13490605	Replace Insulators TL231 - (230kV Bay d'Espoir - Stoney Brook)	137.5
	13490701	Replace Insulators TL234	172.0
	13490702	Replace Bridge - South West River	22.5
	13490703	Replace Insulators TL251, TL252	227.0
	13490705	Install Deadend Structure - Conne River Tap TL220 (69kV Bay d'Espoir - Barachoix)	30.0
	13490708	Wood Pole Line Management Program	248.0
	13500705	Replace Distribution Line- Seal Cove to Pass Island	9.5
	13500706	Upgrade Distribution System - Farewell Head (Lines 2,3)	52.5
	13500708	Replace Distribution Poles -Barachoix	4.0
	13500709	Replace Distribution Line - Brighton	7.5
	13500710	Replace Insulators - Barachoix Line 4	7.5
	13500711	Pine Cove Interconnection	30.0
	13960701	Service Extensions - Labrador Interconnected	9.5
	14270707	Northwest Arm Cottage Development	7.5
	14300702	Safety and Reliability Upgrades - Hawkes Bay Terminal Station	11.5
	18190701	Legal Survey of Distribution Line Right-of-Ways	20.0
	20840603	Portland Creek Development -Feasibility Study	10.0
	20890601	West Coast Communications Study	78.5
Total 2007			1,432.0
2008	12090802	Customer Service Application	14.0
	12900804	Upgrade Spherical Valve Maintenance Seals - Cat Arm	56.0
	12930808	Hydraulic Structure Life Study - Bay d'Espoir	8.0
	12960801	Replace Unit 2 Main Steam Stop Valve - Holyrood	20.0
	12960802	Replace Unit 2 High Pressure Heater - Holyrood	40.5
	12960803	Soot Blowing Controls Study - Holyrood	6.0
	12960804	Replace Unit 1 and 2 Condenser Valve Actuators - Holyrood	17.0
	12960811	Replace Superheater Unit 1 - Holyrood	57.0
	12970804	Precipitator and Scrubber Installation Study - Holyrood	16.0
	13250813	Replace Battery Banks and Chargers - Various Locations	7.5
	13490801	Upgrade Line TL212 - (Come by Chance to Linton Lake)	75.0
	13490803	Replace Insulators TL232 - (230kV Stoney Brook - Buchans)	131.0
	13490808	Wood Pole Line Management Program	252.5
	13500809	Replace Insulators TL253 - (69kV - Jackson's Arm - Coney Arm)	5.5
	13500811	Replace Insulators - Upper Salmon	6.0
	13500812	Replace Insulators - Westport	9.0
	13960804	Upgrade Distribution Line - L11 Wabush	11.0
	14250803	Upgrade Distribution System - Mary's Harbour	15.0
	14250804	Upgrade Distribution System - Port Hope Simpson	7.5
	14270804	Upgrade Distribution System - L3 St Anthony	4.5
	14300702	Safety and Reliability Upgrades - Hawkes Bay Terminal Station	15.0
	18190801	Legal Survey of Distribution Line Right-of-Ways	26.5
20890801	Voice Communications Strategy Study	17.0	