

1 **B-31, Replace Vehicles and Aerial Devices, Various Sites, 2009- \$2,156,400**

2 Q. In the related report it is stated that boom truck V4468 is being replaced  
3 because of its mileage, which is less than 60,000 km, while the criteria for  
4 replacement stated an age of 7 – 10 years or 200,000 km. Please explain  
5 why this boom truck is being replaced at this time.

6

7

8 A. Boom truck V4468 is being replaced because the boom is over 21 years old  
9 and is in need of replacement due to age, wear and rust. The vehicle meets  
10 Hydro's minimum replacement criteria of seven to ten years.