

1 Q. **Re Replace Pumphouse Motor Control Centres, page B- 12**

2 What quantifiable "unreliable system" results or unplanned outages have been
3 caused by deterioration of the Motor Control Centers, as asserted at page 4, section
4 3 of the report supporting this Project? If there have been any such results or
5 outages, can their further occurrence be mitigated in the future by greater
6 preventive maintenance efforts?

7

8

9 A. As stated in Section 3.5 of the report, there are no records or statistics available to
10 determine if a unit failure or outage was directly caused by a failure of the
11 pumphouse motor control centers. Additional preventive maintenance efforts will
12 not eliminate system reliability issues or unplanned outages since the condition of
13 the pumphouse environment continue to cause irreversible deterioration of the
14 motor control centers.