

- 1 **Q. (a) Pertaining to the same Graph referenced in the previous question, does NP**
2 **have an explanation as to why the Actual Peak Load (measured December**
3 **27, 2008) was high relative to the other readings shown in Graph 1.**
4
5 **(b) What was the next highest transformer load reading experienced subsequent**
6 **to the Actual Peak Load shown on Graph 1?**
7
8 A. (a) Yes. See response to Request For Information CA-NP-11
9
10 (b) The peak reading reported on December 27, 2008 was obtained using digital
11 recording ammeters. Due to a metering problem on MOB-T2, it is unknown what
12 other peak loads were experienced subsequent to the Actual Peak Load shown on
13 Graph 1. Please see response to Request For Information CA-NP-11 for further
14 explanation.