1	Q.	Re Sandy Brook Hydro Plant Refurbishment (other) p. 10 of 100 and Tab 1.4.
2		
3		The report at Tab 1.4 is based upon an inspection completed on March 4, 2010
4		Specifically what new information came to the attention of NP on March 4, 2010
5		that was not known to it in June of 2009 when the Company stated that work on
6		Sandy Brook would be taking place in 2014?
7		
8	A.	Report 1.4 Sandy Brook Hydro Plant Refurbishment presents a condition assessment of
9		the plant control, governor, electrical and mechanical systems based on a site inspection
10		completed on March 4, 2010.
11		
12		No such condition assessment was completed at Sandy Brook hydro plant in preparation
13		of the Capital Plan included with the 2010 Capital Budget Application in June 2009. As
14		a result most of the detailed engineering information required to assess the need for
15		refurbishment at the Sandy Brook hydro plant was not compiled in June 2009.
16		
17		For an explanation of how the annual capital budget relates to the 5-year Capital Plan
18		submitted in preceding years please refer to the response for Request for Information CA-
19		NP-27.