

1 Q. Re: Replacement of Stator Windings, Tab 1:

2 Was asbestos found in Units 2 or 4? Is asbestos abatement, if required, a cost  
3 included in this application?  
4

5

6 A. Asbestos was not found in Unit 2 however asbestos was found in Unit 4. There is a  
7 contract already in place for the replacement of stator windings for Bay d’Espoir if  
8 this project is approved. However, asbestos abatement is not itemized in that  
9 contract and its cost is expected to be insignificant. If asbestos is found, the  
10 contractor will be asked to separately identify those removal costs so that it can be  
11 expensed.