

1 Q. With reference to the **Project C-20, Upgrade Vibration Monitoring System**
2 **Holyrood**, at page 12, Volume II, Tab 9, Hydro asserts that a request was made to
3 another Turbine Supervisory Instrumentation system supplier for an alternative but
4 that a complete cost and detailed estimate was not available at the time of the
5 report. What is the name of the other supplier and is a cost and detailed estimate
6 available at this time? If so, please provide same.

7
8
9 A. The alternate Turbine Supervisory Instrumentation System supplier contacted was
10 Hinz, a Rockwell Automation company. Their budgetary proposal was not complete
11 at the time of budget preparation and has not yet been obtained. Other options
12 and vendors will be evaluated during the project planning stage.