Page 1 of 1

| 1 | Q. | 2013 Wood Pole Line Management (WPLM), Appendix B. At pages B6-7, were all of |
|----|----|---|
| 2 | | the mean outage hours in figures 2a, 2b and 2c caused by pole damage or pole |
| 3 | | failure on a Hydro transmission line? If not, please present figures 2a, 2b, and 2c |
| 4 | | with mean outage hours based only on pole damage or pole failures on Hydro |
| 5 | | transmission lines. |
| 6 | | |
| 7 | | |
| 8 | A. | The data presented in figures 2a, 2b and 2c show the mean outage hours for |
| 9 | | transmission line failures caused by pole damage or pole failures on Hydro's |
| 10 | | transmission lines. |