

1 Q. C-22, Tab 10: Upgrade Fuel Oil Day Tank - Holyrood; \$584,200

2 In the report entitled: Upgrade Fuel Oil Day Tank, located in Volume II, Tab
3 10, Hydro states that:

4

5 *"The American Petroleum Institute (API) recommends that tanks, such as the*
6 *daytank at Holyrood, undergo an external inspection every five years and an*
7 *internal inspection every ten years after its initial service date. The required*
8 *inspection procedures are outlined in API Standard 653, Tank Inspection,*
9 *Repair, Alteration, and Reconstruction. The day tank at Holyrood has not*
10 *been inspected since 1998. Therefore, it is recommended that the tank*
11 *undergo a full inspection that is in compliance with the API 653 standard in*
12 *2013."*

13

14 In which year was API Standard 653 published?

15

16

17 A. The first edition of API Standard 653 was issued on January 1, 1991.