

1 **Q. Re: IN-NLH-186, Att.1 (Rev. 1)**

2 For the following unallocated line items, please provide a reasonable estimation as
3 to the proportions that are located in Labrador East and in Labrador West,
4 respectively.

5 If Hydro is unable to make even approximate allocations, please explain why there
6 should be uncertainty as to the location of poles and related equipment, and of
7 "allocated meters".

CLASS – DISTRIBUTION	Unit of Property	Amount
330 – Distribution Primary	T07 – Transformers – Pole Mounted	1,100,000
350 – Distribution Secondary	T07 – Transformers – Pole Mounted	875,000
370 – Distribution Services	T07 – Transformers – Pole Mounted	1,375,000
390 – Poles	P04 – Pole Cribs and Hardware	597,364
	P07 – Poles, Wood	2,211,950
	T07 – Transformers – Pole Mounted	450,000
Allocated meters		2,288,365

8

9

10 **A. Please see Hydro's response to IN-NLH-302.**