1	Q.	The AMEC report, at page 45 of 231, states that:
2		In the years 2010 and 2011, NL Hydro undertook a number
3		of activities with vendors that have the Original Equipment
4		Manufacturer (OEM) rights to the gas turbine sections in
5		order to conduct internal inspections of the individual
6		sections and prepare field inspection reports complete with
7		refurbishment estimates.
8		Provide copies of the field inspection reports complete with refurbishment
9		estimates. In the absence of these reports, provide documentation that authorizes
10		discontinuation of the activities with the vendors that have OEM rights to the
11		Holyrood Gas Turbine sections prior to the receipt of the field inspection reports.
12		
13		
14	A.	The field inspection reports that were made available to AMEC are included in
15		Appendices 9 through 12 of NP-NLH-022 Rev. 1, Attachment 1.