

1 Q. (Hydro Reply Evidence dated August 7, 2015, Section 10, Black Start) Did the
2 Hardwoods gas turbine adequately meet the black start requirement on the Avalon
3 Peninsula during the January 2014 outage events?
4
5

6 A. Refer to Hydro's response CA-NLH-015 in its Application, *Installation of Diesel Units*
7 *for the Purpose of Blackstarting*. Black start of the Holyrood units was not required
8 during the period of supply disruptions on the Island Interconnected System in
9 January 2014.