

1 Q. Sunnyside Replacement Equipment: Please provide all Hydro or AMEC
2 documentation from the 1990s and 2000s addressing analyses regarding installing
3 transformer breakers with 230kV breaker failure protection at Sunnyside and other
4 terminal stations to protect the transmission system from a transformer failure.

5

6

7 A. There is no record of Hydro or AMEC documentation from the 1990s and 2000s
8 specifically addressing this issue. Refer to Hydro's response to PR-PUB-NLH-026 for
9 the background to the status of transformer breakers at Sunnyside and other
10 terminal stations and the proposed analysis regarding installing transformer
11 breakers at Sunnyside and other terminal stations.