

1 Q. Please state whether and on what basis Hydro agrees or disagrees that the cause of
2 malfunction of Western Avalon breaker B1L37 would have been identified and
3 corrected if 6-year maintenance had been conducted prior to the malfunction.

4

5

6 A. Hydro does not believe the cause of the malfunction of Western Avalon breaker
7 B1L37 would have been identified and corrected if six-year maintenance had been
8 conducted prior to the malfunction. The basis for this statement is: (1) following the
9 event the breaker operation was checked and confirmed to operate correctly; and
10 (2) detailed preventative maintenance was completed in July 2014 and no sustained
11 problem was found.