PR-PUB-NLH-080 NLH 2015 Prudence Review

Page 1 of 1

1	Q.	Please provide the number of times Hydro had overhauled type DLF breakers
2		before the Holyrood B1L17 overhaul in 2014.
3		
4		
5	A.	Prior to overhauling Holyrood B1L17 DLF breaker at Holyrood, Hydro overhauled
5		only one DLF breaker which was breaker L05L33 at Buchans Terminal Station.