## Page 1 of 1

| 1  | Q. | Projects over \$50,000 but Less Than \$200,000  |
|----|----|---|
| 2  |    | Tab 8 Replace ABB Exciter Unit 2- Cat Arm:  |
| 3  |    | What is the inventory of parts on hand for the ABB Exciter?                           |
| 4  |    |   |
| 5  |    |   |
| 6  | A. | The available spare parts for the ABB exciter are shown on page 4, Table 1 of the     |
| 7  |    | submitted report. There is, however, an error in the table. The quantity in inventory |
| 8  |    | for the Stabilizing Signal Adapter, ABB Part No. UN0089a-P, should be one rather      |
| 9  |    | than zero. The spare parts list was confirmed by Kestrel Power Engineering during     |
| 10 |    | their assessment and is shown in Appendix D of their report, which is located in      |
| 11 |    | Appendix B of the report submitted for the proposal.                                  |