

1 Q. **C-65; Volume II, Tab 28: Line Depot Condition Assessment and Refurbishment**

2 Has Hydro given any consideration to the requirements of the HVdc transmission  
3 line in relationship to its current line depot locations?

4

5

6 A. Current locations of line depots with respect to the requirements of the HVdc  
7 transmission line were not considered in this application. However, given that the  
8 HVdc line will run adjacent to many of Hydro's HVAC lines, the existing line depots  
9 will be well positioned to service the new line.