

1 Q. **C-65; Volume II, Tab 28: Line Depot Condition Assessment and Refurbishment**
2 Please provide a table showing the sites that will be refurbished in this project
3 (Springdale, Cow Head, and Rocky Harbour) and the cost of refurbishment that can
4 be attributed, from a breakdown of Table 1 on page 8, to each of these sites.

5
6

7 A. Below is a table outlining the refurbishment costs at each site.

8

Project Cost: (\$ x1,000)	Cow Head	Rocky Harbour	Springdale
Material Supply	0	0	0
Labour	69.4	63.8	94.5
Consultant	0	0	0
Contract Work	112	103	152.5
Other Direct Costs	13.5	12.5	18.4
Interest and Escalation	15.8	14.5	21.5
Contingency	39.0	35.9	53.1
TOTAL	249.8	229.7	340.1