

1 Q. Reference: *Gas Generator Engine Refurbishments Hardwoods and Stephenville*,  
2 Page 4, lines 17-18:

3

4 *“In addition, an analysis of each engine failure will be completed. It is anticipated*  
5 *that the findings of this analysis will be available by August 2016.”*

6

7 Will the analysis be completed by Hydro? If not, who will complete the analysis for  
8 Hydro?

9

10

11 A. Alba Power will be disassembling engine serial number 202204 to complete an  
12 analysis to determine the cause of failure. Amec Foster Wheeler (Performance  
13 Improvements) have been hired on behalf of Hydro to witness the disassembly and  
14 participate in the root cause analysis conducted by Alba Power. Engine serial  
15 number 202205 will be refurbished by the successful tenderer and the scope of  
16 work includes failure analysis to determine the root cause of the failure.