

1 Q. **Project D-298: Upgrade Aluminum Support Structure - Holyrood**

2 When did Hydro become aware of the deterioration of aluminum support
3 structures?

4

5

6 A. Hydro became aware of the deterioration of the aluminum support structures in
7 June 2012. The issue was determined after the sudden failure of the anchor bolts
8 on a 230 kV bus structure which required emergency repairs to restore the
9 structure's integrity.