| 1 | Q. | Tab 18; Volume III: Replace Disconnect Switches |
|----|----|---|
| 2 | | Please explain why Hydro's Asset Management Plan does not require tracking of |
| 3 | | the reliability performance of disconnect switches along with the performance of |
| 4 | | terminal stations. |
| 5 | | |
| 6 | | |
| 7 | A. | Currently, Hydro measures reliability performance at the Delivery Point or Terminal |
| 8 | | Station level as a part of Hydro's Corporate key performance indicators for |
| 9 | | reliability. The measurement of reliability at this level is consistent with the |
| 10 | | Canadian Electricity Association and allows Hydro to benchmark our reliability |
| 11 | | indicators with other Canadian Utilities. |
| 12 | | |
| 13 | | Hydro does not track the reliability performance of disconnect switches, as these |
| 14 | | disconnect switches are a sub-component within terminal stations. |