Page 1 of 1

Q. With Reference to Exhibit 44, Holyrood Thermal Generating Station – Condition 1 2 Assessment and Life Extension Study p. 6 of 725, Section Overall Plant Assessment states: "Holyrood is also expected to be able to meet its 2041 end of life date for 3 operation in a synchronous condensing mode, but will require some further 4 5 substantial equipment refurbishments and replacements specific to that role. These 6 are identified later in the report, but examples of these would include generator 7 rewinds, powerhouse and pump house roof replacements, switching yard breakers 8 and motorized switches refurbishments/replacements, and synchronous condensing 9 conversions." Have the costs of these refurbishments and replacements been 10 included in the CPW analysis? 11 12 13 A. Exhibit 44, Holyrood Thermal Generating Station – Condition Assessment and Life 14 Extension Study p. 6 of 725, Section Overall Plant Assessment was completed after 15 the CPW analysis was carried out. Therefore, the particular equipment 16 refurbishments and replacements identified in that report were not included in the

17

CPW analysis.