

1 **Re: Page B-73, Replace Disconnect Switches, \$367,600**

2 Q. Please provide a schedule for the period from 2002 – 2007F showing how  
3 many similar disconnects have been replaced in each year and how many  
4 remain in service.

5

6

7 A. Since 2002, there have been only two similar disconnects replaced. One was  
8 at the Massey Drive Terminal Station in 2002 and the other was at the  
9 Hardwoods Terminal Station in 2006. Overall there are approximately 110  
10 69 kV disconnects in service on the Hydro system.