

1 **Re: Page B89, Replace Line Camp 98 – TL-228**

2 Q. Should this replacement building be constructed, what measures will be  
3 taken to ensure it receives adequate maintenance?

4

5

6 A. The regular preventive maintenance program will be reinstated. Adequate  
7 ventilation and appropriate building materials be incorporated into the design  
8 of the structure to maximize its useful life.