

1 **Re: Page B-117, Replace Diesel Units, \$334,400**

2 Q. Please provide a schedule showing the number of times in each year from
3 2002-2007 Unit 567 has been out of service and the length of each outage.

4

5

6 A. As a result of limited use due to its unreliability, there have been no major
7 maintenance requirements for this unit, and therefore no extended outages.