

1 Q. **Re 2011 Capital Plan - Individual Capital Projects:**

2 **Project B-5, Upgrade Stack Breeching Unit 1:** Appended at the end of the appendix
3 at Volume I, Tab 2, is a 2010-07-02 Alstom letter, which offers clarifications and
4 opinions in relation to the Alstom Engineering Report. At the third page of this
5 letter, it is stated "It is far more difficult to predict the longevity of the repair option
6 and certainly, it will depend on the amount of block removed for casing inspection
7 and repair. If all of the block is removed (old Option A3) and extensive repairs are
8 completed to essentially restore the ductwork to like new condition, then a life of 5
9 years or longer with relatively minor annual repair costs might be a reasonable
10 assumption." Is "old Option A3" the same as Alternative 2 identified in Volume I,
11 Tab 2, pages 14-16, section 4.3)? If not, provide a CBA and Cumulative Present
12 Worth (CPW) for Option A3 based on a study period to 2020, taking into account
13 Holyrood being in standby mode for the period 2016-2020.

14

15

16 A. This proposal will be revised. Please refer to IC-NLH-16 for an explanation.