

1 Q. **Re 2011 Capital Plan - Individual Capital Projects:**

2 **Project B-5, Upgrade Stack Breeching Unit 1:** Presumably, the substantial issues  
3 with the Stack Breeching in Unit 1 have been known to Hydro since the first version  
4 of the Alstom Engineering Report was issued on December 18, 2008. Presumably,  
5 Hydro has taken, over the last 20 months, and will continue to take until  
6 refurbishment or replacement is approved, the necessary interim monitoring and  
7 repair work necessary to prudently manage those issues. What has been the cost  
8 incurred by Hydro in the last months of managing those issues (less the cost of the  
9 Alstom reports) and what is the estimated cost to Hydro of continuing to manage  
10 those issues, in the same manner, to December 2011?

11

12

13 A. This proposal will be revised. Please refer to IC-NLH-16 for an explanation.