## Page 1 of 1

1	Q.	B-5, Upgrade Stack Breeching Unit 1, \$3,553,400
2		In the information provided it is stated that the 1990 replacement of the stack
3		breeching cost \$656,777. Please provide the reasons for the variance between the
4		cost of the 1990 project and the proposed 2011 project.
5		
6		
7	A.	Please see response to IC-NLH-16.