1	Q.	Re: Returbishment of Marine Terminal at the Holyrood Thermal Generating
2		Station (Tab 3)
3		At page B-27, Appendix B, regarding "Inspection", Hatch recommends a detailed
4		inspection of the metal thickness of the jetty piles. Has this inspection been
5		completed? Is it scheduled to be completed?
6		
7		
8	A.	No, the detailed inspection of the metal thickness of the jetty piles has not been
9		completed. It is anticipated that this inspection will be completed in 2012, during
10		the detailed design phase of the project.