

1    Q.    **Re: Project B-9 Replace Fuel Oil Heat Tracing**

2            What was the estimated cost of installing a stainless heat tracing system, as  
3            apparently was recommended by Tyco, in 2002?

4

5

6    A.    The estimated cost of installing the self regulating stainless steel heat tracing  
7            system as recommended by Tyco in 2002 was \$1.12 million.