Page 1 of 1

1	Q.	Refurbishment of the Fuel Oil Storage Facility, Holyrood Thermal Generating
2		<u>Station</u>
3		In Appendix A of the report, page 10 of 248, AITEC recommends, in November
4		2003, that NLH do a 5-year external inspection of Tank #3 in 2008. Was an externa
5		inspection of Tank #3 undertaken in 2008 or at a later date?
6		
7		
8	A.	Please see CA-NLH-6 for response.