

1 Q. On page II-31 of the 2011 Study, one of the locations visited during the 2005 Study
2 is said to be a typical inventory and warehouse yard and an asset recovery yard. As
3 clarification, what were locations of the typical inventory and warehouse yard and
4 asset recovery yard visited during the 2005 Study? What made these sites "typical?"

5

6

7 A. During the 2005 depreciation study Gannett Fleming visited the Bishop's Falls and
8 Port Saunders inventory yards. These yards were considered by Hydro to be two of
9 the inventory and warehouse facilities that would provide Gannett Fleming with an
10 understanding of a variety of inventory items (both new and material for re-use)
11 and yard procedures.